


































SUSPENSIONS - BALLONS

NO. FIRESTONE	DIMENSION HORS-TOUT	DESSUS	BASE	NO. CONCURRENTS
FS-8050				Load Guard SC2052 Navistar 1685174C-1 Turner B4771 36514-013 Goodyear 1R14-039
FS-8709				Hendrickson S21800 (Intraax AA230) 8/97-up) Replaces W01-358-8751 (Approx. 6/98) 9525/NAD-26906 Order No. WC1-358-1690
FS-8710				Hendrickson S22045 (HK230) Approximate availability 1-98 replaces W01-358-8755
FS-8713				Hand Trailer S22949 (Van Traax) used 9525 piston wbumper spacer
FS-8852				Peterbilt 03-07887
FS-9043				Mack 57QL1115

SUSPENSIONS - BALLONS

NO. FIRESTONE	DIMENSION HORS-TOUT	DESSUS	BASE	NO. CONCURRENTS
FS-9122				Load Guard SC2041 Navistar 554772C1 90557020 Neway 90557076 90557077 Reyco 12883-02 Ridewell S-3053-C Tuner 36514-8
FS-9243				Neway 90557112
FS-9265				Turner C20124 Goodyear 1R12-249
FS-9270				Turner C20010
FS-9580				Hendrickson S-20127 HT-250U (9-006) HT-250U-Y (9Y-006) replaces W01-358-9292 (1T15V-11) S-20414